



Material Safety Data Sheet

MSDS HurriView II™ Plaque Indicating Solution

13-November-2006

HurriView II™ PLAQUE INDICATING SOLUTION

Page 1 of 5

CHEMICAL PRODUCT/COMPANY IDENTIFICATION

Material Identification

PRODUCT NAMEHurriView II™ PLAQUE INDICATING SOLUTION
CHEMICAL FAMILYMixture

Company Identification

MANUFACTURER/DISTRIBUTOR

Beutlich® LP Pharmaceuticals
1541 Shields Drive
Waukegan, IL 60085

PHONE NUMBER

Product Information: 1-847-473-1100
1-800-238-8542 (within the United States and Canada)
M-Th: 7:30 a.m. - 5:00 p.m., F: 7:30 a.m. - 4:00 p.m. CT.

Emergency: 1-847-980-0567

COMPOSITION/INFORMATION ON INGREDIENTS

INGREDIENT NAME	CAS NUMBER
D&C RED DYE 28	18472-87-2
FD&C BLUE 1.....	3844-45-9
GLYCEROL	56-81-5
Non-hazardous ingredients including WATER	7732-18-5

HAZARDS IDENTIFICATION

*****EMERGENCY OVERVIEW*****

* Possible eye irritant. Purple solution. *

HurriView II™ PLAQUE INDICATING SOLUTION

Page 2 of 5

Potential Health Effects:

EYE: Contact may cause irritation.

SKIN: Not expected to cause irritation

INGESTION: Should be non-toxic

INHALATION: Irritation of the nose, throat, and lungs may result from over-exposure to vapors or mist.

CHRONIC (CANCER) INFORMATION: Not classified as carcinogenic

LONG TERM TOXIC EFFECTS: None known

FIRST AID MEASURES

First Aid

INHALATION: Remove to fresh air.

SKIN CONTACT: Wash thoroughly.

EYE CONTACT: Irrigate eyes with running water for at least 15 minutes. Get medical attention if irritation develops.

INGESTION: None applicable

FIRE FIGHTING MEASURES

Not a fire hazard

EXTINGUISHING MEDIADry Chemical; Carbon Dioxide; Foam; Water spray for large fires

SPECIAL FIRE FIGHTING PROCEDURES.....As for surrounding fire

ACCIDENTAL RELEASE MEASURES

Safeguards (Personnel)

NOTE: Review FIRE FIGHTING MEASURES and HANDLING (PERSONNEL) sections before proceeding with clean-up. Use appropriate PERSONAL PROTECTIVE EQUIPMENT during clean-up.

HANDLING AND STORAGE

Store under ambient conditions. No special handling required.

HurriView II™ PLAQUE INDICATING SOLUTION

Page 3 of 5

EXPOSURE CONTROLS/PERSONAL PROTECTION

EYE PROTECTION REQUIREMENTS:.....None
SKIN PROTECTION REQUIREMENTS:.....None
RESPIRATOR REQUIREMENTS:.....None
VENTILATION REQUIREMENTS:.....If needed, use local exhaust ventilation to keep airborne concentrations below the TLV.

Exposure Guidelines
Exposure Limits

GLYCEROL (as mist)
PEL (OSHA): 10mg/m3 total
TLV (ACGIH): 10mg/m3 total

PHYSICAL AND CHEMICAL PROPERTIES

PHYSICAL FORM..... Purple liquid

STABILITY AND REACTIVITY

STABILITY: This is a stable material.
HAZARDOUS POLYMERIZATION:..... Will not occur
INCOMPATIBILITIES:..... None special

TOXICOLOGICAL INFORMATION

Mixture not tested but based on components:
May cause eye irritation.
None of the components are listed as carcinogens.

ECOLOGICAL INFORMATION

No data

DISPOSAL CONSIDERATIONS

Waste Disposal:
Treatment, storage, transportation, and disposal must be in accordance with applicable Federal, State/Provincial, and Local regulations.

HurriView II™ PLAQUE INDICATING SOLUTION

Page 4 of 5

TRANSPORTATION INFORMATION

DOT – not regulated

REGULATORY INFORMATION

U.S. Federal Regulations

TSCA Inventory Status: Reported/Included

Section 313 Supplier Notifications.

This product contains no toxic chemicals subject to the reporting requirements of Section 313 of the Emergency Planning and Community Right-To-Know Act of 1986 and of 40 CFR 372.

Canadian Regulations:

DSL: included

WHMIS Classification: none

European Regulations: EINECS: all chemicals listed

EEC Classifications: none

OTHER INFORMATION

STATE RIGHT-TO-KNOW LAWS

No substances on the state hazardous substances list, for the states indicated below, are used in the manufacture of products on this Material Safety Data Sheet, with the exceptions indicated. While we do not specifically analyze these products, or the raw materials used in their manufacture, for substances on various state hazardous substances lists, to the best of our knowledge the products on this Material Safety Data Sheet contain no such substances except for those specifically listed below:

WARNING: SUBSTANCES KNOWN TO THE STATE OF CALIFORNIA TO CAUSE CANCER:
None known

WARNING: SUBSTANCES KNOWN TO THE STATE OF CALIFORNIA TO CAUSE BIRTH DEFECTS
OR OTHER REPRODUCTIVE HARM: None known

This information is furnished without warranty, expressed or implied, except that it is accurate to the best knowledge of Beutlich® LP Pharmaceuticals. The data on this sheet relates only to the specific material designated herein. Beutlich® LP Pharmaceuticals assumes no legal responsibility for use or reliance upon these data.

HurriView II™ PLAQUE INDICATING SOLUTION

Page 5 of 5

Responsibility for MSDS:

Beutlich® LP Pharmaceuticals
1541 Shields Drive
Waukegan, IL 60085

MADE IN U.S.A.

HurriView II is a trademark of Beutlich® LP Pharmaceuticals.